## FITNESS CERTIFICATE FOR SCHOOL BUILDINGS

Name of Officer

: Akhil G

Name of School

: Baselios Vidyanikethan Senior Secondary School

Location with name of Education 3

Ernakulam District,

District/Sub -District

Thripunithura Sub-District.

1) Basement Floor RCC roof

Clacification of the buildings as specified in col 4 of the application for fitness

2) Ground floor RCC roof

: 3) First floor RCC roof

Certificate

4) Second floor Sheet roof (false ceiling and electrification done)

Period for which the certificate is issued

: 2023-24

Nature of defect. if any

a) Foundation and basement

b) Superstructure

c) Doors and windows

Nil

d) Wood work wrought & put up

e) Roof

f) Flooring

Any major defects modified which will render the building unsafe in any manner

Whether maintenance works have been done properly

: Yes

Whether the structure is sound or not for

conducting classes

Sound under normal weather condition this Certificate is : subject to the approval of DEO, whether the size of class

room as per KER

Certified that the school was inspected by me on 29.05.2023 and found to be fit to conduct classes for the period 2023-24 (academic Year)

Place: Mulamthuruthy Date: 30/05/2023



