FITNESS CERTIFICATE FOR SCHOOL BUILDINGS

1 Name of Officer

: AKHIL G

Name of School

: Baselios Vidyanikethan Senior Secondary School

Location with name of Education

District/Sub -District

Ernakulam District,

Thripunithura Sub-District.

1) Basement Floor RCC roof

Clacification of the buildings as specified in

4 col 4 of the application for fitness

Certificate

2) Ground floor RCC roof

: 3) First floor RCC roof

4) Second floor Sheet roof (false ceiling and electrification

done)

Period for which the certificate is issued

6 Nature of defect. if any

a) Foundation and basement

b) Superstructure

c) Doors and windows

d) Wood work wrought & put up

e) Roof

f) Flooring

Any major defects modified which will render the building unsafe in any manner

Whether maintenance works have been

done properly

Whether the structure is sound or not for conducting classes

: 2024-25

Nil

: Yes

Sound under normal weather condition this Certificate is : subject to the approval of DEO, whether the size of class

room as per KER

Certified that the school was inspected by me on 16.05.2024 and found to be fit to conduct classes for the period 2024-25(academic Year)

Place: Mulamthuruthy Date: 16/5/2024



